

Ningbo Sanyou Environmental Protecting Technology Co.,Ltd

Technical Report:	Apr,01.2017
Ningbo Sanyou Environmental Protecting Technology Co.,Ltd	

Sample Description: Four Drum Spill Pallet (See below)

Manufacturer: / Sample Quantity: /
Buyer: / Product Type /
Country of Origin: China Country of Destination: /
Color: / SKU No.: /
Protocol No.: / Previous Report No.: /

EXECUTIVE SUMMARY:

Test Item	Result	Remark
1.Compression test	See below	See below

REMARK:

Reference to client Requirement

BVCPS (shanghai) contact information for this report

Technical Questions:

Primary Contact: Wayne Liu 24166755, E-mail: Wayne.liu@cn.bureauveritas.com Back-Up Contact: Ham Sun 24166749, E-mail: Ham.sun@cn.bureauveritas.com

Concerns About Billing and General Inquires:

Primary Contact: Jonny Wang 24166801, E-mail: Jonny-s wang@cn.bureauveritas.com

Back-Up Contact: Connie Zhou 24166816, E-mail: Connie.zhou@cn.bureauveritas.com

BUREAU VERITAS
CONSUMER PRODUCTS SERVICE DIVISION (SHANGHAI)

ANDY WANG



Technical Report: Ningbo Sanyou Environmental Protecting Technology Co.,Ltd Apr.01.2017 Page 2 of 3

Test Item:

Sample Description:

No.	Name	Model	Weight(g)	Size(mm)	Category
1	Four Drum Spill Pallet	UP-1401/1402	41150	1330X1330X430	Two blue plastic grid add one yellow plastic pallet

Test item:

Take the sample into the equipment, Opening the testing machine, pressure on the sample for 220N to make the sampe with the pressure plate normal contact, pressure speed is 3mm/min, when the pressure reached 5000kgf to stop the test.

Test Result:

No.	Test Result	
1	No damage was observed on the sample after test	



Technical Report: Ningbo Sanyou Environmental Protecting Technology Co.,Ltd Apr.01.2017 Page 3 of 3

Sample Pictures



1#

