

CONSUMER PRODUCTSSERVICES DIVISION VERITAS

Ningbo Sanyou Environmental Protecting Technology Co., Ltd

Technical Report:

Apr,01.2017

Ningbo Sanyou Environmental Protecting Technology Co.,Ltd

Sample Description:	Four Drum Spill Pallet(See below)		
Manufacturer:	/	Sample Quantity:	/
Buyer:	/	Product Type	/
Country of Origin:	China	Country of Destination:	/
Color:	/	SKU No.:	/
Protocol No.:	/	Previous Report No.:	/

EXECUTIVE SUMMARY:

Test Item	Result	Remark
1.Compression test	See below	See below

REMARK:

Reference to client Requirement

BVCPS (shanghai) contact information for this report

Technical Questions:Primary Contact:Wayne Liu24166755, E-mail: Wayne.liu@cn.bureauveritas.comBack-Up Contact:Ham Sun24166749, E-mail: Ham.sun@cn.bureauveritas.com

Concerns About Billing and General Inquires:

Primary Contact: Jonny Wang 24166801, E-mail: Jonny-s wang@cn.bureauveritas.com Back-Up Contact: Connie Zhou 24166816, E-mail: Connie.zhou@cn.bureauveritas.com

> BUREAU VERITAS CONSUMER PRODUCTS SERVICE DIVISION (SHANGHAI)

ANDY WANG



Test Item:

Sample Description:

No.	Name	Model	Weight(g)	Size(mm)	Category
1	Four Drum Spill Pallet	UP-1403	1	1330X1330X430	Two metal grid add one yellow plastic pallet

Test item:


Take the sample into the equipment, Opening the testing machine, pressure on the sample for 220N to make the sampe with the pressure plate normal contact, pressure speed is 3mm/min, when the pressure reached 5000kgf to stop the test.

Test Result:

No.	Test Result	
1	No damage was observed on the sample after test	




Technical Report: Ningbo Sanyou Environmental Protecting Technology Co.,Ltd Apr.01.2017 Page 3 of 3



Sample Pictures

1#



- End of Report -